

## Exercise 4A

### Instructions:

1. Start a **New** file using either the **inch-helper.dwt** or the **metric-helper.dwt**
2. Set **Units** and **Precision**:  
**Units = Fractional** for inch users or **Decimal** for metric users.  
**Precision = 1/2"** for inch users or **0** for metric users.
3. Set **Drawing Limits**:  
Lower Left corner = **0,0** Upper Right Corner = **20,15**  
[**508,381** metric users].
4. Make sure you use **Zoom / All** after setting Drawing Limits.
5. Erase the rectangle that appears with the template. It will appear too small.
6. Turn **off** the **Snap** and **Ortho**.  
(Your cursor should move freely.)
7. Draw the objects shown using:  
Circle, Center Radius, and Line (Use Layer = Object Line) Object Snap = Center and Tangent
8. **Save** the drawing as: **Ex-4A**

