


## Exercise 4C

### Instructions:

1. Start a **New** file using either the **inch-helper.dwt** or the **metric-helper.dwt**
2. Set **Units** and **Precision**:  
**Units = Architectural** for inch users or **Decimal** for metric users.  
**Precision = 1/2"** for inch users or **0** for metric users.
3. Set **Drawing Limits**:  
Lower Left corner = **0,0** Upper Right Corner = **25,20**  
[**635,508** metric users].
4. Make sure you use **Zoom / All** after setting Drawing Limits.
5. Erase the rectangle that appears with the template.
6. Turn **off** the **Snap** and **Ortho**.
7. Draw the objects shown using:  
Line (Use Layer = Object Line)  
Object Snap = Perpendicular
8. **Save** the drawing as: **Ex-4C**



Start by drawing this line,  
then use Object Snap  
**Perpendicular** to draw  
the other lines.