







## Exercise 7C

### Instructions:

1. Start a **New** file using either the **inch-helper.dwt** or the **metric-helper.dwt**
2. Draw the three rectangles shown below.
3. Chamfer the corners using the **Chamfer** command.
4. **Save** the drawing as: **Ex-7C**



Before Chamfer



After Chamfer